













SIDEWALK DEFICIENCY CODES WITH DESCRIPTION

Windsor Heights Public Works

Repair Code	Description		
A	This sidewalk is cracked with a vertical edge of more than one inch high. This may be a one or two panel replacement	 <p>1" or more</p>	
B	Sidewalk raised more than 2 inches in 8 feet from normal profile line of sidewalk	 <p>2" or more</p>	
C	Sidewalk sunken more than 2 inches in 8 feet from normal profile line of sidewalk	 <p>2" or more</p>	
D	The sidewalk is cracked into 3 or more pieces AND there is either a vertical discontinuity of greater than one-half inch or horizontal gap of greater than one-half inch or portions are missing or pitted.	 <p>1/2" or more</p>	

SIDEWALK DEFICIENCY CODES WITH DESCRIPTION

Windsor Heights Public Works

Repair Code	Description		
E	Sidewalk cross slope is incorrect, greater than .5 inch in 1 foot; within the margin of error and.		
F	Sidewalk cracked and/or spalled (small crater line holes deeper than 3/8 inch with part of sidewalk missing, forming holes deeper than 3/8 inch.		
G	Sidewalk missing panels.	